























Q-05

ASSEMBLING INSTRUCTION

<p>AX1</p> 	<p>GX1</p> 	<p>①</p> 	<p>②</p> 	<p>③</p> 
<p>Bx1</p> 	<p>H x 1</p> 	<p>④</p> 	<p>⑤</p> 	<p>⑥</p> 
<p>Cx1(LxR)</p> 	<p>I x 12</p>  <p>M6x20mm</p>	<p>⑦</p> 	<p>⑧</p> 	
<p>DX1</p> 	<p>J x 3</p>  <p>M8x20mm</p>			
<p>EX1</p> 	<p>K x 3</p>  <p>M8x16mm</p>			
<p>Fx5</p> 	<p>L x 3</p>  <p>M8x16mm</p>			
	<p>M x 1</p> 			
	<p>N x 5</p>  <p>M6x14mm</p>			