






















Q-09

ASSEMBLING INSTRUCTION

<p>AX1</p> 	<p>GX1</p> 	<p>①</p> 	<p>②</p> 
<p>Bx1</p> 	<p>H x 4</p>  <p>M6x20mm</p>	<p>③</p> 	<p>④</p> 
<p>Cx1(LxR)</p> 	<p>I x 4</p>  <p>M6x25mm</p>	<p>⑤</p> 	<p>⑥</p> 
<p>DX1</p> 	<p>J x 4</p>  <p>M8x40mm</p>		
<p>EX1</p> 	<p>K x 1</p> 		
<p>Fx5</p> 	<p>L x 4</p> 		
	<p>M 1 x 1</p>  <p>M6</p>		
	<p>M 2 x 1</p>  <p>M8</p>		
	<p>N x 5</p>  <p>M6x14mm</p>		