






PARTS LIST:


A-1PC




B-1PC




C-2PCS




D-2PCS




E-1PC




F-2PCS




G-1PC




H-1PC



I-1PC



J-2PCS




K-1PC



L-2PCS




M-2PCS



N-1PC



O-32PCS




P-32PCS




Q-16PCS




R-2PCS



S-2PCS






T-1PC




HARDWARE LIST:


1 -1PC	2 -24PCS	3 -16PCS
		
4 -12PCS	5 -61PCS	6 -61PCS
		
7 -8PCS	8 -1PC	9 -4PCS
		
10 -9PCS		
		




step 4




step 6




step 5




step 7




step 8



step 10



step 9



step 11

