

















PARTS LIST:


A  Headboard=1pc	B  Footboard=1pc	C  Supporting block on SR=2PCS
D  Siderail=2pcs	E  Support block on footboard=1PC	F  Metal side support rail=2PCS
G  Support block on headboard=1PC	H  Metal Centre cross rail=1PC	I  Non-woven fabric=1PC
J  Metal block=2PCS	K  Metal corner block=2PCS	L  Fabric Handle=1PC
M  Slat=16PCS	N  End cap=32PCS	O  Gas Lift Mechanism=2PCS
P  Metal Centre cross rail=1PC		

HARDWARE LIST:


① Allen Key $\varnothing 5/16"$ =1pc	② Bolt $\varnothing 5/16"$ X $3/4"$ L=20 pcs	③ Bolt $\varnothing 5/16"$ X $1-1/2"$ L=16 pcs
		
④ Bolt $\varnothing 5/16"$ X $2"$ L= 4 pcs	⑤ Flat Washer $\varnothing 5/16"$ X $\varnothing 19$ mm=48 pcs	⑥ Spring Washer=48 pcs
		
⑦ Nut=4 pcs	⑧ Wrench=1 pc	⑨ Nut=4 pcs
		
⑩ Bolt $\varnothing 5/16"$ X $1"$ L=8 pcs		
		




step 4




step 6




step 5




step 7



step 8



step 9



step 10

